


# Tuning Chart and String Gauges

*James Jones - Tsimbl*  
13/12



I use number designations for wire sizes  
Their actual diameters are as follows.

PB is short for Phosphor-Bronze  
W for Wound

4 = .013  
5 = .014  
6 = .016  
7 = .018  
8 = .020  
9 = .022

To order replacements contact me  
by phone or e-mail indicating the  
gauge and number desired and if  
you need loop ends. I will ship  
immediately and bill you for the  
strings.

James Jones Instruments  
1384 Colton Mills Rd.  
Bedford, VA 24523  
540 586-6319  
e-mail [james@jamesjonesinstruments.com](mailto:james@jamesjonesinstruments.com)  
Visit my web site!  
[jamesjonesinstruments.com](http://jamesjonesinstruments.com)

Steel are .75, PBs are \$1 each, wound  
are \$1.25