


Tuning Chart and String Gauges

James Jones
Custom Performance
Model 4/19/18/8



Treble 2

Treble 1

Bass 1

Bass 2

I use number designations for wire sizes
Their actual diameters are as follows.

PB is short for Phosphor-Bronze
W for Wound

3 = .012
4 = .013
5 = .014
6 = .016
7 = .018
8 = .020
9 = .022
10 = .024
23PB = .0226

James Jones Instruments
1384 Colton Mills Rd.
Bedford, VA 24523
540 586-6319
e-mail james@jamesjonesinstruments.com
Visit my web site!
jamesjonesinstruments.com